

Valerie Ontiveros

Thank you & have a great day!

Attached to this fax is the Procedure 5 letter for the subject property located at 7803 Puritan St., Downey, CA 90242. If you have any questions or need further information please contact me at (714) 871-8711.

Good Afternoon Mr. Mann,

For Review Please Reply Your Sampling Results Your Report

Re: Procedure 5 Letter

Phone:	Project #
Fax: 888-875-6779	Date: April 14, 2008
Co:	Pages:
To: Mr. Bryan Mann	From: Valerie Ontiveros

Fax

1519 E. Chapman Avenue, #A
Fullerton, California 92831
(714) 871-8711 Fax (714) 871-8712

Titan Environmental
Solutions, Inc.



April 11, 2008

South Coast Air Quality Management District Headquarters
21865 East Copley Drive
Diamond Bar, California 91765-4182

RE: **PROCEDURE-5 ASBESTOS SITE CLEAN-UP PLAN**

Griffin Residence
7803 Puritan Street
Downey, California 90242
SCAQMD Notice to Comply No.: D16352
SCAQMD Approval No.: Pending

Dear Sir or Madam:

Titan Environmental Solutions, Inc is submitting a Procedure-5 work plan on behalf of Bill Griffin in an effort to comply with SCAQMD. This abatement action is categorized as a Procedure-5 based on the condition of the asbestos-containing materials identified in the asbestos survey/Assessment and the need to modify standard abatement protocol due to current site conditions.

On April 5th of 2008, a Titan Environmental representative arrived on site to perform an Asbestos survey/assessment of suspect materials that were impacted by the recent renovation activities. The Titan Environmental Representative collected a total of twenty seven PLM bulk samples and submitted to an approved NVLAP laboratory for analysis, the results are as follows, Acoustic Ceiling Material 3% Chrysotile, Linoleum Flooring 70% Chrysotile & a six inch by eight foot transit pipe was assumed these materials were scattered throughout the entire property including the crawl space. Titan Environmental recommended to the owner Mr. Griffin a procedure 5 clean up due to the condition of the asbestos containing materials identified in the survey.

Findings:

The following materials were found to contain asbestos in concentrations greater than 1%

- White Acoustic Ceiling Material (dispersed throughout the interior and exterior of the house including the crawl space)
Approximately 3,400 sq. ft.
- Linoleum Flooring Material (Throughout kitchen)
Approximately 200 sq. ft.
- 4 inch Transit Pipe (In construction debris pile at the Southeast corner of property)
Approximately 5 sq. ft.

The results of this sampling can be found as an attachment to this document.

- Removal and disposal of all acoustic ceiling material, transite pipe and construction debris piles outside of the residents as asbestos waste within a regulated area (Approximately 1,400 sq. ft.).
- Removal and disposal of all acoustic ceiling material and linoleum flooring throughout the interior of the residents as asbestos waste within a full containment (Approximately 2,000 sq. ft.).
- Removal and disposal of all ducting throughout the interior of the residents as asbestos waste within a full containment (Approximately 1,200 sq. ft.).
- To prevent asbestos fibers from being re-suspended, the ACM should be wet down with amended water.
- Large pieces of ACM shall be picked up and burnt-to-wrapped in 6 mil plastic sheeting, labeled as asbestos containing material and disposed of as asbestos waste by the abatement contractor.

Scope of Work:

The impacted area(s) of the subject property are now vacant; Titan Environmental advised Mr. Griffin to stop all work seal up, lock all doors and windows throughout the house. The majority of contents within impacted area(s) were present at the time of the site visit.

Property Occupancy:

- Approximately 3,400 sq. ft. of acoustic ceiling material is scattered in various locations throughout the interior and exterior of the residence including the crawl space.
- Approximately 200 sq. ft. of linoleum flooring material was found in the kitchen.
- Approximately 1,200 sq. ft. of ducting throughout the plenum.
- A 6 Inch X 8 Foot transite pipe was found in construction debris pile at the southeast corner of the backyard.

Impacted Area(s):

Type: Single Family Residence - Single Story
 Circa: 1970-80's
 Size: Approximately 1,900 S.F. total

Building Information:

Source: Renovation
 Type of damage: Physical,
 Date of renovation: March 2008
 Date of survey: April 5th, 2008
 Contractor: Sky Blue Environmental, Inc.
 Consultant: Titan Environmental Solutions, Inc. Robert Menald 714-871-8711

Background Information:

The work covered by this Procedure-5 Plan includes furnishing all required labor, equipment, materials, and transportation necessary for the proper and safe removal/decontamination, handling, and disposal of the listed materials found within the inside and outside of the subject property during this project. Work shall be performed in accordance with applicable regulations and the following procedure outline.

Griffin Residence
 7803 Puritan Street, Downey, California 90242
 April 11, 2008

- California Code of Regulations (CCR)
 - Title 8
 - 8 CCR 341.6 TO 341.15
 - 8 CCR 1529
- Code of Federal Regulations (CFR) Publications
 - 29 CFR 1910.134
 - 29 CFR 1910.145
 - 29 CFR 1926.1101
 - & 1926.58
 - 40 CFR 61
 - 40 CFR 61
- Subpart A General Provisions
 - Subpart B National Emission Standard for Hazardous Air Pollutants
- Asbestos
 - Prevention Signs and Tags
 - Specifications for Accident
 - Respiratory Protection

Our work procedures are planned, documented, and performed in compliance with the following regulations and specifications:

Governing Regulations: All work performed by the Contractor will be in accordance with these written procedures. In conducting our research, we have collaborated with the governmental regulatory agencies including the U.S. Environmental Protection Agency (U.S. EPA), the U.S. Occupational Safety and Health Administration (OSHA), the State of California Department of Health Services (DHS), the California Department of Industrial Relations Division of Occupational Safety and Health (Cal/OSHA), and the National Institute of Occupational Safety and Health (NIOSH).

B. **Staging of Supplies:** Supplies will be staged in a neat and orderly manner and will be coordinated with the designated Owner's Representative.

- SCAQMD (Emergency)
- Cal-OSHA (24-Hr.)

A. **Agency Notifications:** This regulatory notice allows for notification to the proper governmental agencies of work to be performed, prior to starting date.

Mobilization: The mobilization phase, which includes agency notifications and staging of supplies, will take place once a verbal notice to proceed has been issued and this Procedure-5 has been approved by SCAQMD.

- Small asbestos pieces of debris should be properly wetted placed in six (6) mil poly bags (double bagged), sealed, labeled and disposed of as asbestos waste.
- Soil in affected crawl space area(s) shall be raked, and placed into double 6 mil poly bags (double bagged), sealed, labeled and disposed of as asbestos waste.
- Hard surfaced/non-porous building surfaces will be wet-wiped (Approximately 5,500 sq. ft. of surface area).
- Removal and disposal of remaining contaminated soft/porous contents and electronics/appliances as asbestos contaminated waste (Approximately 5 cu. yd.).
- Remove and disposal of carpet and carpet pad as asbestos contaminated waste.

American National Safety Institute (ANSI) Publications
-ZP 279 Fundamentals Governing the Design and Operation
of Local Exhaust Systems
-Z88.280 Practices for Respiratory Protection
American Society for Testing and Materials (ASTM)
National Institute for Occupational Safety and Health (NIOSH)
77-173 NIOSH Occupational Exposure Sampling Strategy Manual
South Coast Air Quality Management District Rule 1403SCAQMD HEPA negative air machine
permits, proper emergency notification, proof of payment and worker certifications will be
submitted to SCAQMD prior to commencement of work.

Personal Air Monitoring: (Contractor)

Personal sampling is conducted during the abatement project to determine employee's exposure (outside any respirator) to airborne fibers. Representative, daily personal monitoring during the abatement project is required by (OSHA Asbestos Standard Title 8 1529 and 29 CFR 1926.1101) and the contractor's work policy. Moreover, every contractor worker shall have the right to know the asbestos concentrations to which they are exposed and what measures are being taken to protect them. This information will be made available to the employee on a daily basis. Also, results of personal sampling shall be used to select proper respiratory protection for the abatement worker. Data from personal monitoring can be used as an indication of effective removal and control techniques, which result in the lowest employee exposure.

Respiratory \ Worker Protection: (Contractor)

Respiratory protection for this project will be HEPA filtered respirators. All personnel will be required to wear proper protective clothing, which will include hooded Tyvek suits, gloves, and boots. The contractor will be responsible for total compliance with all applicable OSHA guidelines including but not limited to: 29 CFR 1926.1101 and Title 8 1529.

GENERAL APPROACH

Decontamination and Gross Removal:

This process will involve the thorough decontamination and gross removal of the impacted areas throughout the interior and exterior of the property in accordance with all applicable Federal, State, and Local regulations. All critical barriers will be sealed; a 3-stage decontamination unit will be constructed for entry/exit, the interior of the residents will be placed under negative air pressure utilizing negative air machines with HEPA filtration. The contractor will then proceed to conduct necessary gross removal and clean-up utilizing manual/wet methods (see Scope of Work). Upon completion of initial clean-up, HEPA vacuuming and wet wiping of all surfaces starting from top to bottom will begin. At this point the on-site consultant will visually inspect the affected work area(s) to determine if all debris and visible dust has been removed and bagged for disposal. Upon passing "final visual review," air clearance samples will be collected only inside the resident's containment and analyzed by the consultant utilizing phase-contrast microscopy (PCM) to determine if the decontamination work is complete. When the clearance criteria has been met (<0.01 f/cc), the contractor will then encapsulate the interior of the containment.

Air Monitoring:

Air monitoring will take place while the entire abatement procedures; the locations for the sampling pumps will be at the discretion of that on-site representative.

A Certified Site Surveillance Technician (CSST) and/or a Certified Asbestos Consultant (C.A.C.) representing the owner shall perform a final visual inspection, air clearance sampling, soil sampling (crawl space) and TEM Dust MicroVac sampling. Clearance levels shall be less than 0.01 fibers per cubic centimeters (f/cc) for PCM air samples.


Worker Decontamination:

The contractor will have a 3-stage decontamination unit on-site. The contractor will be responsible for total compliance with all applicable OSHA guidelines including but not limited to: 29 CFR 1926.1101 and Title 8 1529.

Transport and Disposal:

All asbestos containing and asbestos contaminated materials removed from the site will be properly characterized and labeled and bagged as asbestos waste and placed into a disposal bin for transport to a disposal site. The waste material will be properly manifested prior to removal from the project site and signed for by a representative of the owner.

Certified Asbestos Consultant (C.A.C.)



Robert Menald,
DOSH CAC No. 94-1509

Griffin Residence
7803 Puritan Street, Downey, California 90242
April 11, 2008

SCAQMD
(NEG AIR REG. NUMBERS)

Grittm Residence
7803 Puritan Street, Downey, California 90242
April 11, 2008

L

SCAQMD
(PROCEDURE-5 NOTIFICATION W/ PROOF OF PAYMENT)

Griffm Residence
7803 Puritan Street, Downey, California 90242
April 11, 2008

ASBESTOS REPORT

Griffin Residence
7803 Puritan Street, Downey, California 90242
April 11, 2008

TABLE 1 ASBESTOS ANALYTICAL RESULTS

Subject Property:

7803 Puritan Street,
Downey, CA 90242

The following homogeneous building material types were sampled as part of this survey and their results are summarized in the table below:

SAMPLE NO.	MATERIAL DESCRIPTION	SAMPLE LOCATION	F/NF ¹	COND. ²	% ACM	# SAMP.	APPX. QUANTITY
0405-01-01 0405-01-02 0405-01-03	Plaster Wall	W. end of the Living Room's S. Wall Center of Bedroom #2's S. Wall S. end of Bedroom #1's E. Wall	F	Significantly Damaged	ND	3	8,690 SF
0405-02-04 0405-02-05 0405-02-06	Button Board	W. end of the Living Room's S. Wall Center of Bedroom #2's S. Wall S. end of Bedroom #1's E. Wall	NF	Significantly Damaged	ND	3	6,690 SF
0405-03-07 0405-03-08 0405-03-09	Linoleum Flooring	N end of Restroom #1 W. end of Restroom #1 S. W. end of Restroom #1	NF	Significantly Damaged	ND	3	65 SF

Abbreviations: N=North, E=East, W=West & S=South
ND=None Detected

¹F = Friable; NF = Non-friable

²Cond. = Condition of Materials-Good, Damaged, or Significantly Damaged.

Note: <1% = Calif. Code of Regulations, Title 8, Section 1529, "Asbestos-containing construction material" means any manufactured construction material which contains more than one tenth of 1 percent asbestos by weight. This material will be abated as asbestos containing material; however, it may be disposed of as construction debris

ASBESTOS ANALYTICAL RESULTS CONT

Subject Property:

7803 Puritan Street,
Downey, CA 90242

The following homogeneous building material types were sampled as part of this survey and their results are summarized in the table below:

SAMPLE NO.	MATERIAL DESCRIPTION	SAMPLE LOCATION	F/NF ¹	COND. ²	% ACM	# SAMP.	APPR. QUANTITY
0405-04-10	Linoleum	N. end of Kitchen	NF	Significantly Damaged	70% Chrysotile	3	330 SF
0405-04-11	Paper Backing	W. end of Kitchen	NF	Significantly Damaged		3	330 SF
0405-04-12							
0405-05-13	Vapor Barrier	S. end of the Family Room's W. Wall	NF	Significantly Damaged		3	1,950 SF
0405-05-14	Paper	Debris pile at the S.E. of the Back Yard	NF	Significantly Damaged		3	1,950 SF
0405-05-15		Debris pile at the S.W. of the Back Yard	NF	Significantly Damaged		3	1,950 SF
0405-06-16		N. end of Family Room Closet	NF	Significantly Damaged		3	680 SF
0405-06-17	Drywall	Center of the Kitchen Pantry's N. Wall	NF	Significantly Damaged		3	680 SF
0405-06-18		Center of the Kitchen Pantry's S. Wall	NF	Significantly Damaged		3	680 SF

Abbreviations: N=North, E=East, W=West & S=South
ND=None Detected

¹F = Friable; NF = Non-friable

²Cond. = Condition of Materials-Good, Damaged, or Significantly Damaged.

Note: <1% = Calif. Code of Regulations, Title 8, Section 1529, "Asbestos-containing construction material" means any manufactured construction material which contains more than one tenth of 1 percent asbestos by weight. This material will be abated as asbestos containing material; however, it may be disposed of as construction debris.


LABORATORY ANALYTICAL RESULTS

ATTACHMENT 1

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. Samples reported as <1% or none detected may require additional testing by TEM to confirm asbestos quantities. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of LA Testing. LA Testing's liability is limited to the cost of analysis. LA Testing bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted.
 NPLAP Lab Code 101324-0, CAL EAP # 1406

Analysts)
 Fred Chappelle (27)

Derrick Tanner, Laboratory Manager
 or other approved signatory



Sample	Location	Appearance	% Fibrous	% Non-Fibrous	% Type
0405-01-01	West end of living room S. wall	Beige/White Non-Fibrous	15% Mica	85% Non-fibrous (other)	None Detected
0405-01-02	Center of bedroom #25 S. wall	Beige/White Non-Fibrous	15% Mica	85% Non-fibrous (other)	None Detected
0405-01-03	South end of bedroom #1 S.E. wall	Beige/White Non-Fibrous	15% Mica	85% Non-fibrous (other)	None Detected
0405-02-04	West end of the living room S. wall	White/Beige Fibrous	5% Cellulose	15% Mica	80% Non-fibrous (other)
0405-02-05	Center of bedroom #25 S. wall	White/Brown Fibrous	15% Cellulose	85% Gypsum	None Detected
0405-02-06	South end of bedroom #1 S.E. wall	White/Brown Fibrous	15% Cellulose	85% Gypsum	None Detected
0405-03-07	North end of restroom #1	White/Gray Fibrous	20% Cellulose	<1% Glass	<1% Synthetic
330803182-0007		Heterogeneous			None Detected

Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Customer ID: 3211TA85
 Customer PO:
 Received: 04/07/08 8:00 AM
 LA Testing Order: 330803182
 LA Testing Proj:
 Analysis Date: 4/8/2008
 Report Date: 4/8/2008

Abn: Veronica Quiroz
 Titan Environmental
 1519 E. Chapman, A
 Fullerton, CA 92831
 Project: 172308AS Grinn Residence
 Phone: (714) 871-8711
 Fax:

LA Testing
 10772 Noel St., Los Alamitos, CA 90720
 Phone: (714) 828-4339 Fax: (714) 828-4344 Email: losalamitos@latesting.com



Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. Samples reported as <1% or none detected may require additional testing by TEM to confirm asbestos quantities. The above test report relates only to the fibers tested and may not be reproduced in any form without the express written approval of LA Testing. LA Testing's liability is limited to the cost of analysis. LA Testing bears no responsibility for sample collection practices or analytical methods implemented. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted.
 NMLAP Lab Code: 101384-0, Cal ELAP # 1405

Fred Chappelear (27)

Derrick Tamer, Laboratory Manager
 or other approved signatory

Analysis

Sample	Location	Appearance	% Fibrous	% Non-Fibrous	% Types
0405-03-08	West end of Bedroom #1	Fibrous	<1% Glass	<1% Synthetic	None Detected
0405-03-09	Southwest end of restroom #1	White/Gray Fibrous	20% Cellulose	80% Non-fibrous (other)	None Detected
0405-04-10	North end of kitchen	Gray Fibrous	20% Cellulose	10% Non-fibrous (other)	70% Chrysotile
0405-04-11	West end of kitchen	Gray Fibrous	30% Cellulose	10% Non-fibrous (other)	60% Chrysotile
0405-04-12	Center of the kitchen	Gray Fibrous	30% Cellulose	10% Non-fibrous (other)	60% Chrysotile
0405-05-13	South end of family room W. wall	Brown Fibrous	81% Cellulose	15% Non-fibrous (other)	None Detected
0405-05-14	Debrisat the south east of the backyard	Brown Fibrous	80% Cellulose	20% Non-fibrous (other)	None Detected

Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Attn: Veronica Quiroz
Titan Environmental
1519 E. Chapman, A
Fullerton, CA 92831
 Project: 172308AS Griffin Residence
 Phone: (714) 871-8711
 Fax: (714) 871-8711
 LA Testing Proj: 4/8/2008
 Analysis Date: 4/8/2008
 Report Date: 4/8/2008
 Customer ID: 3217A86
 Received: 04/07/08 8:00 AM
 LA Testing Order: 330803192

LA Testing
 10772 Noel St., Los Alamitos, CA 90720
 Phone: (714) 828-4999 Fax: (714) 828-4944 Email: info@latingesting.com



Due to magnification limitations inherent in PLM asbestos fibers in dimensions below the resolution capability of PLM may not be detected. Samples reported as <1% or none detected may require additional testing by TEM to confirm asbestos quantities. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of LA Testing. LA Testing's liability is limited to the cost of analysis. LA Testing bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results and the responsibility of the client. Samples received in good condition unless otherwise noted.
 NVLAP Lab Code 101384-0, Cal ELP # 1408

Darick Tanner, Laboratory Manager
 or other approved signatory

Fred Chappkear (27)
 Analyst(s)

Sample	Location	Appearance	% Fibrous	% Non-Fibrous	% Type Asbestos
0405-05-15	Debris pile at southwest end of the backyard	Black Fibrous	80% Cellulose	20% Non-fibrous (other)	None Detected
0405-06-16	North end of family room closet	White/Brown Fibrous	20% Cellulose	80% Gypsum	None Detected
0405-16-17	Center of the kitchen pantry north wall	White/Brown Fibrous	20% Cellulose	80% Gypsum	None Detected
0405-16-18	Center of the kitchen pantry south wall	White/Brown Fibrous	20% Cellulose	80% Gypsum	None Detected
0405-07-19	North end of family room closet	White Non-Fibrous	90% Ca Carbonate	10% Non-fibrous (other)	<1% Chrysotile
0405-07-20	Center of the kitchen pantry north wall	White Non-Fibrous	90% Ca Carbonate	10% Non-fibrous (other)	<1% Chrysotile
0405-07-21	Center of the kitchen pantry south wall	White Non-Fibrous	90% Ca Carbonate	10% Non-fibrous (other)	<1% Chrysotile
0405-08-22	South east corner of living room ceiling	White Fibrous	5% Mica	92% Non-fibrous (other)	3% Chrysotile

Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Attn: Veronica Quiroz
Titan Environmental
1519 E. Chapman, A
Fullerton, CA 92831
 Project: 172308AS Griffin Residence
 Phone: (714) 871-8711
 Fax: (714) 871-8711
 LA Testing Proj: 330803152
 LA Testing Order: 330803152
 Received: 04/07/08 8:00 AM
 Customer PO: 32117A85
 Report Date: 4/8/2008
 Analysis Date: 4/8/2008

10772 Noel St., Los Alamitos, CA 90720
 LA Testing
 Phone: (714) 828-4339 Fax: (714) 828-4344 Email: test@titanenvironmental.com

THIS IS THE LAST PAGE OF THE REPORT.

PLM-1

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. Samples reported as <1% or none detected may require additional testing by TEM to confirm asbestos quantities. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of LA Testing. LA Testing's liability is limited to the cost of analysis. LA Testing bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted.
 NVLAP Lab Code 1013840, CA ELAP # 1406

Derrick Tanner, Laboratory Manager
 or other approved signatory

Fred Chappelle (27)

Analysis



Sample	Location	Appearance	% Fibrous	% Non-Fibrous	% Type
0405-08-23	Debris pile next to entrance door at N.W. corner	White Fibrous		98% Non-Fibrous (other)	2% Chrysotile
0405-08-24	Debris pile at N.E. corner of bedroom #1	Beige Fibrous		5% Mica 92% Non-fibrous (other)	3% Chrysotile
0405-09-25	Debris pile at the center of the telephone data	White/Beige Fibrous	60% Cellulose 35% Min. Wool	5% Non-fibrous (other)	None Detected
0405-09-26	Debris pile at the southwest end of kitchen	White/Beige Fibrous	60% Cellulose 35% Min. Wool	5% Non-fibrous (other)	None Detected
0405-09-27	South west corner of restroom #1	Beige Fibrous	96% Cellulose	5% Non-fibrous (other)	None Detected

Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Amr: Veronica Quiroz
 Titan Environmental
 1519 E. Chapman, A
 Fullerton, CA 92831
 Project: 17230AS Giffm Residence
 Fax: (714) 871-8711
 Phone: (714) 871-8711
 Customer ID: 3271A85
 Customer PO: 04/07/08 8:00 AM
 Received: LA Testing Order: 330803182
 LA Testing Proj: 330803182
 Analysis Date: 4/8/2008
 Report Date: 4/8/2008

LA Testing
 10772 Noel St., Los Alamitos, CA 90720
 Phone: (714) 838-4339 Fax: (714) 838-4944 Email: kosta@lating.com



CHAIN OF CUSTODY

ATTACHMENT 2

LA Testing, Inc. • LOS ANGELES - 714-528-4000 • CALIFORNIA

Prepared by: [Signature]
Reviewed by: [Signature]
Checked by: [Signature]

Date: 4/14/08
Date: 4/14/08
Date: 4/14/08

Time: 6:00
Time: 6:00
Time: 6:00

Sample Number	Material	Location	Quantity
01-01	Particle	WEST END OF THE LIVING ROOMS & UNIT	6.6905F
01-02	Particle	WEST END OF THE BEDROOMS	6.6905F
01-03	Particle	SOUTH END OF THE BEDROOM # 2	6.6905F
01-04	Particle	WEST END OF THE LIVING ROOMS SOUTH	6.6905F
01-05	Particle	CENTRE OF THE BEDROOM # 2S	6.6905F
01-06	Particle	SOUTH END OF THE BEDROOM # 1S UNIT	6.6905F
01-07	Particle	NORTH END OF THE BEDROOM # 1S UNIT	6.6905F
01-08	Particle	WEST END OF THE BEDROOM # 1	6.6905F
01-09	Particle	SOUTH END OF THE BEDROOM # 1	6.6905F
01-10	Particle	NORTH END OF THE BEDROOM # 1	6.6905F
01-11	Particle	WEST END OF THE KITCHEN	6.6905F
01-12	Particle	CENTRE OF THE KITCHEN	6.6905F
01-13	Particle	EAST END OF THE KITCHEN	6.6905F
01-14	Particle	WEST END OF THE LIVING ROOMS	6.6905F
01-15	Particle	CENTRE OF THE LIVING ROOMS	6.6905F
01-16	Particle	EAST END OF THE LIVING ROOMS	6.6905F
01-17	Particle	CENTRE OF THE LIVING ROOMS	6.6905F
01-18	Particle	WEST END OF THE LIVING ROOMS	6.6905F
01-19	Particle	SOUTH END OF THE LIVING ROOMS	6.6905F
01-20	Particle	CENTRE OF THE LIVING ROOMS	6.6905F
01-21	Particle	EAST END OF THE LIVING ROOMS	6.6905F
01-22	Particle	CENTRE OF THE LIVING ROOMS	6.6905F
01-23	Particle	WEST END OF THE LIVING ROOMS	6.6905F
01-24	Particle	CENTRE OF THE LIVING ROOMS	6.6905F

LA Testing, Inc. • 159 Pasadena Avenue, S. Pasadena, CA 91105 • 10772 Noel Street, Los Angeles, CA 90028

3808 031 02

LA Testing, Inc. • LOS ALAMITOS - 714-828-4000 • CERRITOS

608

4/7/08

LA Testing, Inc.

Received
Received
Received
Received

8" x 8" Transit Pipe 6 inch wide stored outside in debris
pit of the south end corner of building
Removal of debris material (PCM)
Contains


Sample Number	Material	Location
04/05/08-25	DOWN IN ACTS INSULATION	DEBRIS PILE AT THE CENTER OF THE SECTION DECOMPOSE AT THE SOUTH END OF CRUSHED SOUTH WEST CORNER OF THE RESTROOM #1
26		
27		

Quantity

LA Testing, Inc. • 159 Pasadena Avenue S. Pasadena, CA 91106
18772 Noel Street, Los Alamitos, CA 90720
8308 031 82

SITE DRAWING

FIGURE 1



TITAN ENVIRONMENTAL SOLUTIONS, INC.

1519 E. CHAPMAN AVENUE, SUITE-A
FULLERTON, CA. 92831

DATE: 04-5-08
FIGURE: FIG-1

PROJ. NO.: 172308-AS
DRAWN BY: Veronica

SCALE: NTS
CHECK BY: ROBERT

GRIFFIN RESIDENCE
LIMITED ASBESTOS SURVEY
7803 PURITAN STREET
DOWNEY CA 90242

CONTAINS WOOD