


# TB078 (Rev1) - Common Wiring Problems

---

This picture shows some of the wiring problems that have been found in Centroid controls. Steps **must** be taken to avoid these problems.



---

## Document History

Rev1 Created on **1999-11-24**